

Dolby® Conference Phone Release Notes

Version 3.0.3.55 (3.0.3)

Release Date: Mon 15th August, 2016

This document provides information about the Dolby Conference Phone 3.0.0 release, including the latest product features, bug fixes, known issues, and upgrade instructions.

See the *Dolby Conference Phone Administrator's Guide v3.0* and *User's Guide* for detailed product specifications and operating instructions.

1 New Features since the 2.1 release

Features introduced in this release.

Dolby Reference	Summary
n/a	n/a

Features introduced in the 3.0.2 release.

Dolby Reference	Summary
DCEP-2775	Provide support for EAP-PEAP with Windows Authentication server.
DCEP-2839	Provide an ability to accept certificates within Out of Box wizard when EAP-PEAP is used.
DCEP-2794	Disable LLDP and DHCP VLAN detection when the user selects a Highfive Room Box from the out of box wizard.

Features introduced in the 3.0.1 release.

Dolby Reference	Summary
DCEP-2761	Improve how the time is configured during Out-of-Box wizard for Highfive configurations.

Features introduced in the 3.0.0 release.

Dolby Reference	Summary
DCEP-2446	Conferencing application development framework with the ability to customize and expedite application development on the Dolby Conference Phone. Controlled availability targeting select service providers.
DCEP-2496	The Out of Box setup wizard now supports new ways of discovering the provisioning server or Dolby Conferencing Console.

Confidential information for Dolby Laboratories Licensees only. Unauthorized use, sale, or duplication is prohibited.

Dolby and the double-D symbol are registered trademarks of Dolby Laboratories. All other trademarks remain the property of their respective owners.

© 2014 Dolby Laboratories, Inc. All rights reserved.

Dolby Laboratories, Inc.

100 Potrero Avenue

San Francisco, CA 94103-4813

T 415-558-0200

F 415-645-4000

DCEP-2480	Introduced user preference to turn off system notification sounds including the boot up welcoming sound. (Preferences.SystemNotificationSounds)
DCEP-2473	The HTTP user agent field now contains the Serial Number and MAC Address.
DCEP-2462	Dolby Conferencing Console Cloud Deployment Model is now supported.
DCEP-2449	Support secure encrypted network packet capture for advanced diagnostics.
DCEP-2445	DNS SRV records may now be used to locate a provisioning server.
DCEP-2731	The serial number is now provided in the Contact field in the SIP INVITE for Dolby Voice calls.
DCEP-2724	The User Interface process is now restarted when it encounters a crash to avoid a reboot.
DCEP-2688	MTLS (Mutual TLS) is now supported in provisioning and by the conferencing application.
DCEP-2647	The device now reboots to complete a software upgrade if there's not enough memory available to complete a software download.
DCEP-2637	The phone now downloads the certificate first then proceeds to download the configuration files.
DCEP-2619	Time zone information is now included in the CDR log.
DCEP-2575	The configuration change user acceptance screen is now optional. (Provisioning.CfgChange.UserAcknowledgementEnabled)
DCEP-2574	IP Address Conflict is now shown as a warning in the Web User Interface.
DCEP-2532	The time zone and network configuration screens have been switched in the Out of Box Wizard.
DCEP-2530	The CA certificate may now be loaded through the Web User Interface.
DCEP-2528	The message displayed on the UI when the phone is challenged for 802.1x authentication has been improved.
DCEP-2501	Out of Box Wizard support for provisioning discovery is now supported.
DCEP-2483	Inbound RTP port ranges for IP PBX calls are now enforced.
DCEP-2479	In the Out of Box Wizard the user name and password entry screens for provisioning are only prompted when the provisioning server challenges the user for authentication.
DCEP-2464	Multiples of 10ms G.711/G.722 packet sizes for IP PBX mode calls are now supported.
DCEP-2438	Debug command message output is now available in the shell in addition to the Web User Interface.
DCEP-2435	Regular SIP registration events have been suppressed to avoid flooding the syslog file.
DCEP-2429	DCP status parameters are now included in the log package downloaded from the phone Web User Interface.
DCEP-2414	The OOM (Out of Memory) kill report now includes more information.
DCEP-2409	The Web User Interface SIP Registration Response is now more meaningful when a TLS error occurs.
DCEP-2397	Periodic memory usage reports are now included in the phone log.
DCEP-2369	Added TLS debug message to clearly display validation mismatch between server CN and DUT's outbound proxy.
DCEP-2361	SIP log messages are now left aligned in the log to improve readability.
DCEP-1847	'Help' has been moved from under Tools, to the top level tab in the phone Web User Interface.
DCEP-2743	It is now possible to disable embedded User Interface system alarms to avoid annoying end users. (Preferences.ShowSystemWarning)
DCEP-2451	DNS status for the secondary network has been added.
DCEP-2459	Multiple tunnels and SIP URIs (failover) for BT MeetMe with Dolby Voice calls are now available.

DCEP-2456	Calls are automatically terminated after a timeout if user forgot to end a call.
DCEP-2425	Project code entry is now supported in BT MeetMe with Dolby Voice calls.
DCEP-2521	BT MeetMe with Dolby Voice calls now use version 2 Join via SIP CCAPI.
DCEP-2503	A DTMF keypad has been added to the BT MeetMe with Dolby Voice active call screen.
DCEP-2498	The phone has improved handling of BT MeetMe version 1 passcodes that are provisioned for Dolby Voice.
DCEP-2494	The phone is automatically activated when the BT MeetMe with Dolby Voice activation PIN is changed.
DCEP-2458	The GeoTrust Primary CA certificate is now included.
DCEP-2454	The translation of "Active Speaker" in German is now correct.
DCEP-2471	The passcode entry keypad now generates a key tap sound to provide input feedback.
DCEP-2450	The Web User Interface now includes a BT MeetMe with Dolby Voice Diagnostic function to make test calls.
DCEP-2432	A button has been added to the active talker screen to allow user to go back to the full roster control screen.
DCEP-2424	BT registration may now be cleared from the Web User Interface.
DCEP-2365	A configuration error is now reported if the Dolby Voice codec specification fails validation.

2 Fixes since the 2.1 release

Fixes introduced in this release

Dolby Reference	Summary
DCEP-2848	The "Network Authentication Required" message no longer stays on screen after a transient authentication failure.

Fixes introduced in the 3.0.2 release

Dolby Reference	Summary
DCEP-2797	Fix User Interface becoming unresponsive after a CSAF app call ends with HTTP proxy enabled.
DCEP-2789	Fix CSAF app SIP calls failing three or four times after a reboot.
DCEP-2796	Fix intermittent certificate configuration problem after CSAF app is rebooted or restarted.
DCEP-2785	Hide Personal when it is configured but BT MeetMe is not.
DCEP-2833	Fix Out-of-band DTMF signaling for BT MeetMe calls.

Fixes introduced in the 3.0.1 release

Dolby Reference	Summary
DCEP-2767	Factory reset now sets the default time to software build time after factory reset.

Fixes introduced in the 3.0.0 release

Dolby Reference	Summary
DCEP-2639	Suppress subsequent successful DHCP log messages after the first one.
DCEP-2609	When user puts "http://" or "https:" in the provisioning server address it creates a weird user experience.
DCEP-2569	Syslog message review to make them less noisy and for Non- Debug level messages make them more readable.
DCEP-2556	Multiple http backend core dumps observed in Dolby IT's DCC deployment.
DCEP-2523	Every time the language changes the UI process leaks 6MB memory.
DCEP-2477	Sip.Account.SelfPort upper limit of port number 9999 causes device to become unresponsive to further configuration.
DCEP-2433	User Feedback icon (thumbs up/down) does not show up in the CDR.
DCEP-2430	Error message is now corrected when trying to push Preferences.Localization.TimeFormat to the phone.
DCEP-2428	Support ptime in SIP SDP to indicate the local preference of packetization interval for IP PBX calls.
DCEP-2426	Misleading error message on the phone is now fixed when the Dolby Conference Console's default pool has password enabled.
DCEP-2418	When the device failed registration because of realm configuration error, the SIP registration status is set as Not Applicable.
DCEP-2416	PJSIP stops sending registration in case of 2-nd 401 response with the same nonce and stale is set to false.
DCEP-2413	Race condition in PJSIP when both PBX accounts register concurrently after network issue.
DCEP-2408	The phone's LLDP packets have incorrect MGMT IP address.
DCEP-2405	The phone continuously reboots request where network is unreachable.
DCEP-2400	IP Network/Status shows "Hostname resolvable" as alarm when user sets the phone to use static IP address.
DCEP-2399	Change the word "Succeed" to "Successful" in the phone UI.
DCEP-2396	Intermittently the phone does not complete reboot as instructed from the device Web UI or sometimes DDMS due to high memory utilization.
DCEP-2390	Device crash with core.pj_pjsua.gz
DCEP-2384	Network Policy Tagged bit is set incorrectly.
DCEP-2370	Unable to remove WPAD URL link from DCP when DDMS is used, failed to communicate with DDMS..
DCEP-2359	Enhancement: Hide or gray out "Secure Media" for Non-TLS transport.
DCEP-2349	If WPAD enable then network status screen should display WPAD first then PAC file.
DCEP-2134	Provisioning Server Address should only allow 4 octets of dot-decimal notation.
DCEP-2398	Sometimes when accepting provisioning server certificate the popup shows empty value.
DCEP-2443	Username (Sip.Account.UserName) parameter is not as per specification (RFC 3261).
DCEP-2710	A wrong value of time is displayed on Total Duration.
DCEP-2709	Invalid email formats are being accepted but the UI message isn't clear on what's wrong.
DCEP-2475	Long meeting names are cropped on the connecting screen.
DCEP-2733	Secondary VLAN proxy with no authentication does not work.
DCEP-2589	Non ASCII character in the display name result in the service rejecting the set name property call and end up as "Restricted" in the roster list.

DCEP-2495	Re-register with BT when the PIN code changes from the provisioning server and if the device has not been registered with BT yet.
DCEP-2467	Do not disturb is not grayed out under the blue mode call "more" menu when the parameter is provisioned.
DCEP-2612	Primary VLAN Network status is in alarm in a scenario where there's server configuration problem for PAC download.

3 Notes

Please refer to the configuration reference material in the *Dolby Conference Phone Administrator's Guide v3.0* for updated configuration parameters supporting new features.

4 Known Issues

Dolby Reference	Summary	Significance/Impact	Workaround
DCEP-2755	The phone will intermittently crash and generate a core file if the SIP transport type is set to Auto and the SIP outbound proxy server becomes unreachable.	If the crash occurs during a call the call could be interrupted. A core file is generated which will consume log space on the provisioning server.	There are two work arounds, either of which will avoid the problem: 1) Do use transport type of Auto, instead specify TCP or UDP. 2) Configure a reliable and reachable outbound call proxy.

5 Installation and Upgrade Procedure

The procedure described in section 5.2 "Upgrading and Downgrading the Software on the Dolby Conference Phone" of the *Dolby Conference Phone Administrator's Guide v3.0* should be followed to install or upgrade to the firmware in this release.